USAAEFA PROJECT NO. 83-17





AD-A140 882

PRELIMINARY AIRWORTHINESS EVALUATION OF THE UH-60 HELICOPTER WITH T700-GE-701A ENGINES INSTALLED

JOHN I. NAGATA
PROJECT OFFICER / ENGINEER

LORAN A. HAWORTH CPT, TC PROJECT PILOT JOE MIESS CW4, AV PROJECT PILOT

FINAL REPORT

AUGUST 1983



DITICE OF THE PARTY OF THE PART

APPROVED FOR PUBLIC RELEASE; DISTRIBUTION UNLIMITED.

UNITED STATES ARMY AVIATION ENGINEERING FLIGHT ACTIVITY = EDWARDS AIR FORCE BASE, CALIFORNIA 93523

84 05 07 005

USAAEFA

FILE CO

DISCLAIMER NOTICE

The findings of this report are not to be construed as an official Department of the Army position unless so designated by other authorized documents.

DISPOSITION INSTRUCTIONS

Destroy this report when it is no longer needed. Do not return it to the originator.

TRADE NAMES

The use of trade names in this report does not constitute an official endorsement or approval of the use of the commercial hardware and software.

SECURITY CLASSIFICATION OF THIS PAGE (When Date Entered)

REPORT DOCUMENTATION PAGE	READ INSTRUCTIONS BEFORE COMPLETING FORM
	3. RECIPIENT'S CATALOG NUMBER
USAAEFA PROJECT NO. 83-17 AD-A140 8	
4. TITLE (and Subtitle)	5. TYPE OF REPORT & PERIOD COVERED
PRELIMINARY AIRWORTHINESS EVALUATION OF THE UH-60A HELICOPTER WITH T700-GE-701A	24-25 JUNE 1983 FINAL
ENGINES INSTALLED	6. PERFORMING ORG. REPORT NUMBER
7. AUTHOR(4)	8. CONTRACT OR GRANT NUMBER(s)
JOHN I. NAGATA JOE MTRSS	a. CONTRACT ON GRANT NUMBER(3)
LORAN A. HAWORTH	
9. PERFORMING ORGANIZATION NAME AND ADDRESS	10 BROGBAN EL ENENT BROJECT TARV
US ARMY AVN ENGINEERING FLIGHT ACTIVITY	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
EDWARDS AIR FORCE BASE, CA 93523	/ 1K-1-DT041-01-1K-1K
	4:
11. CONTROLLING OFFICE NAME AND ADDRESS	12. REPORT DATE
US ARMY AVIATION SYSTEMS COMMAND (PROV) 4300 GOODFELLOW BOULEVARD	13. NUMBER OF PAGES
ST. LOUIS, MO 63120	47
14. MONITORING AGENCY NAME & ADDASSIII different from Controlling Office)	15. SECURITY CLASS. (of this report)
	UNCLASSIFIED
	154. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report)	<u> </u>
Approved for public release; distribution unlimited.	
,	
17. DISTRIBUTION STATEMENT (of the ebstreet entered in Block 20, if different fre	m Report)
16. SUPPLEMENTARY HOTES	
,	
16. KEY WORDS (Continue on reverse olds if necessary and identify by block number)	
Engine Evaluation T700-GE-701A Engine UH-60A Helicopter	inory evaluations
UR-60A Helicopter	Tan 1933, -
St. ABSTRACT (Combins on reverse side if necessary and identity by block number)	
The US Army Aviation Engineering Flight Activity con	ducted a limited Prelimina
Mirworthiness Evaluation of the T700-GE-701A Angina	inetallation in the INLEAS
Helicopter on 24 and 25 June 1983. The evaluation	as conducted at the Sikorsky

Airworthiness Evaluation of the T700-GE-701A engine installation in the UR-60A Helicopter on 24 and 25 June 1983. The evaluation was conducted at the Sikorsky Flight Test facility at West Palm Beach, Florida (field elevation 28 ft) on aircraft S/N 77-22714. The evaluation consisted of three flights for a total of 4.8 productive flight hours. The significant increase in power available for single engine contingencies (262 shaft horsepower (22%) at 4000 ft pressure.

DD 176 TO 1473 EDITION OF 1 HOV 65 IS OSSOLETE

A CONTRA LINESCENSIA L'ESCENCE L'ARTER DE L'ESCENCE BROTHER MANNES L'ESCENCE BROTHER DE L'ESCENCE BROTHER DE L

SECURITY CLASSIFIC STION OF THIS PAGE (When Date Shife

altitude, 95°F) is an enhancing characteristic. The excellent torque matching engine stability and rotor speed control with one engine in electrical control unit lockout and the power lever set for level flight at 80 knots indicated sirspeed is also an enhancing characteristic for the T700-GE-701A engine aswell as the T700-GE-700 engine. The UH-60A acceleration, deceleration, and normal maneuvering response characteristics are essentially the same with either the T700-GE-700 engine or T700-GE-701A engine installed. shortcomings were identified: (1) the slow engine acceleration during collective pulls from approximately zero torque to 50% or greater torque; and (2) the rotor droop to less than 95% rotor speed during collective pulls from zero torque and during aggressive maneuvers such as a quick stop from the maximum airspeed in level flight. During the evaluation a popping sound was noted during collective pulls to approximately 80% and greater torque settings. This popping sound was subsequently identified as "oil canning" on the fuselage skin between the pilot's station and gunner/crew chief's window. (approximate fuselage station 262).

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE(When Date Entered)



DEPARTMENT OF THE ARMY MEADQUARTERS, US ARMY AVIATION SYSTEMS COMMANS 4300 GOODFELLOW BOULEVARD, ST. LOUIS, MO 43120

DRSAV-E

SUBJECT:

Directorate for Engineering Position on the Final Report of USAAEFA Project No. 83-17, Preliminary Airworthiness Evaluation of the UH-60A

Helicopter with T700-GE-701A Engines Installed

SEE DISTRIBUTION

- 1. The purpose of this letter is to establish the Directorate for Engineering position on the subject report. The subject evaluation was conducted to determine the compatibility of the T700-GE-701A engines in the production UH-60A in lieu of the T700-GE-700 engines. The significantly increased performance of the T700-GE-701A engine will enhance the capabilities of the UH-60A at the increased gross weights with Extended Stores Support System (ESSS). It also will increase safety at the lighter gross weights, particularly with the increased shaft horse-power (SHP) using contingency power under single engine conditions.
- 2. This Directorate agrees with the report conclusions and recommendations. Based on the flight test results, the T700-GE-701A engine is compatible with the UH-60A.

FOR THE COMMANDER:

Acces	sion For	
NTIS	GRA&I	di i
DTIC	TAB	15
Unann	Unannounced 🔲	
Justification		
Ву		· · · · · · · · · · · · · · · · · · ·
Distribution/		
Avai	lability	Codes
	Avail and	l/or
Dist	Special	l '
l]	
A /	1	
AT		

RONALD E. GORMONT
Acting Director of Engineering

TABLE OF CONTENTS

		Page
INT	RODUCTION	
	Background	1
	Test Objective	ī
	Description	ī
	Test Scope	ī
	Test Methodology	ī
		•
RES	ULTS AND DISCUSSION	
	General	4
	Engine Acceleration	4
	Engine Deceleration	5
	Pull-Up and Push-Over	5
	Static Droop Characteristics	5
	Quick Stop	5
	Longitudinal Flare Deceleration	6
	Jump Takeoff	6
	Engine Stability	6
	Engine Electrical Control Unit (ECU) Lockout	7
	Contingency Power	7
	Miscellaneous	8
CON	CLUSIONS	
	General	9
	Enhancing Characteristics	9
	Shortcomings	9
	SHOFF CONTRIBETOR OF THE SHOPE O	,
REC	OMMENDATIONS	10
APP	ENDIXES	
A.	References	11
B.	Engine Description	12
C.	Instrumentation	13
D.	Test Techniques and Data Analysis Methods	15
Ē.	Test Data	19
		.,

DISTRIBUTION

INTRODUCTION

BACKGROUND

1. The US Army Aviation Research and Development Command tasked the US Army Aviation Engineering Flight Activity to plan, conduct, and report on a Preliminary Airworthiness Evaluation (PAE) of the Sikorsky UH-60A Helicopter with General Electric T700-GE-701A engines installed (ref 1, app A).

TEST OBJECTIVE

2. The objective of this PAE was to obtain flight test data for qualification of the T700-GE-701A installation in the UH-60A helicopter.

DESCRIPTION

3. The test aircraft was modified to accept the prototype External Stores Support System and the T700-GE-701A engines. The aircraft description with the T700-GE-701A is defined in the UH-60A preliminary Prime Item Development specification (ref 2, app A). The T700-GE-701A engine is defined in the preliminary model specification (ref 3). The T700-GE-701A changes include a 10 minute power rating and a 2.5 minute contingency power rating (CPR). The 2.5 minute rating provides an increase of 262 shaft horsepower (SHP) (22%) at 4000 ft pressure altitude (Hp), 95°F. A more detailed description is contained in appendix B.

TEST SCOPE

4. The T700-GE-701A PAE was conducted at the Sikorsky West Palm Beach Test Facility, on 24 and 25 June 1983, for a total of 4.8 productive flight hours. All test support, including maintenance, servicing, chase, standby crash rescue helicopter and craw, office space, data reduction and final data plots were provided by Sikorsky. Flight restrictions and operating limitations observed during the evaluation are contained in the operator's manual (ref 4, app A) and the airworthiness release (ref 5). Testing was conducted in accordance with the test plan (ref 6) at the conditions shown in table 1.

TEST METHODOLOGY

5. The flight test data were obtained from test instrumentation and recorded on magnetic tape installed in the aircraft. A

Table 1. Test Conditions

Test	Pressure Altitude (ft)	Calibrated Airspeed (kt)	Remarks
Engine Acceleration ²	3000	80	2 rates, several power settings to IRP ³
Engine Deceleration ²	3000	80	2 rates, several power settings to autorotation
Pull-Up and Push-Over	3000	80 to ${ m v_H}^4$	2 rates of application
Static Droop	Surface ⁵ to 1000	80 to V _{NE} 6 to 0	Trim rotor speed on ground at flat pitch, fly envelope without retrimming
Quick Stop	1000	V _H to 0	2 rates
Longitudinal Flare Deceleration	1000	V _H to 0	2 rates, fixed collective (altitude change acceptable)
Jump Takeoff	Surface ⁵	0	2 rates
Engine Stability	3000	80	Collective and pedal pulses
ECU Lockout	3000	80	Torque matching engine stability and rotor speed control with one engine in ECU lockout
Contingency Power	1000	80	Power limits

NOTES:

THE PERSON OF THE PROPERTY OF THE PERSON OF

Engine Start Gross Weight = 17,500 lb, longitudinal center of gravity = 354 in., (mid), rotor speed = 258 RPM

²Single engine and dual engines

³IRP = intermediate rated power

VH = the maximum airspeed in level flight at intermediate rated power

⁵Field elevation = 28 feet 6V_{ME} = never exceed airspeed

detailed listing of the test instrumentation is contained in appendix C. Flight test techniques described in references 7 and 8, appendix A were used. A discussion of the test techniques and data analysis methods is contained in appendix D. A Cooper-Harper Handling Qualities Rating Scale (HQRS) (fig. 1, app D) was used to augment pilot comments relative to handling qualities. Time histories of selected parameters were computer printed.

THE SECOND SECON

RESULTS AND DISCUSSION

GENERAL

6. A limited PAE of the T700-GE-701A engine installation on the UH-60A was conducted at 3000 feet pressure altitude. The contingency power capability was evaluated at 1000 feet Hp. The CPR of the T700-GE-701A engine is an enhancing capability which provides an added margin of safety for emergency single engine operations. The excellent torque matching engine stability and rotor speed control with one engine in electrical control unit (ECU) lockout and the power lever set for level flight at 80 knots indicated airspeed (KIAS) is also an enhancing characteristic. The UH-60A acceleration, deceleration, and normal maneuvering response characteristics are essentially the same with either the T700-GE-700 engine or T700-GE-701A engine installed. shortcomings were identified: (1) the slow engine acceleration during collective pulls from approximately zero torque to 50% torque or greater power settings, and (2) the rotor droop to less than 95% rotor speed (NR) during collective pulls from zero torque and during aggressive maneuvers such as a quick stop from the maximum airspeed in level flight ($V_{\rm H}$). A popping sound determined to be "oil canning" was heard at approximately fuselage station 262 when collective was increased to approximately 80% torque or greater.

ENGINE ACCELERATION

7. Engine acceleration time histories are presented in figures 1 through 6, appendix E. T700-GE-701A acceleration rates appeared to be unchanged from T700-GE-700 accleration rates. Comparative -700 acceleration rates are presented in figures 5 and 6, appendix E. Torque matching during dual engine collective pulls was generally excellent (within approximately 1%). One to two second collective pulls from zeró torque to 50% torque or greater resulted in a transient rotor droop below 90% N_R (91% N_R is minimum transient). Collective pulls from 20% torque or greater to intermediate rated power (IRP) did not result in rotor droop below 95%. The transient rotor droop, below 95%, caused the audio and visual warning systems to activate. These warning signals and the accompanying aircraft yaw oscillations caused the pilot to divert his attention inside the cockpit resulting in loss of outside cues of vertical and lateral obstacle separation. The slow engine acceleration and resulting rotor speed droop degrades the aircraft's capabilities to perform aggressive maneuvers such as high rate descents to cover, masking/remasking, and quick stop. The slow engine acceleration from near zero torque to 50% or greater power settings is a shortcoming.

The transient rotor droop to less than 95% N_R during collective pulls from approximately zero torque to 50% torque or greater, and during aggressive maneuvers such as a quick stop from $V_{\rm H}$ and the resulting aircraft response is a shortcoming.

ENGINE DECELERATION

8. The T700-GE-701A engine deceleration characteristics were evaluated at the conditions shown in table 1. Representative time histories are presented in figure 7 and 8, appendix E for dual and single engine collective reductions. The most aggressive collective reductions (from IRP to full down collective in approximately 2 seconds) resulted in approximately a 4% power turbine speed (Np) overshoot (107% is allowed for up to 12 seconds). However, the recovery (approximately a 30% collective pull from zero torque) resulted in a significant NR droop to about 96% for the dual engine recovery, and a NR droop to about 93% (minimum transient NR droop is 91%) for the single engine recovery for a 37% collective pull. The T700-GE-701A engine deceleration characteristics are satisfactory.

PULL-UP AND PUSH OVER

9. The engine/airframe response characteristics during pull-ups and push-overs were evaluated at the conditions shown in table 1. A time history is presented in figure 9, appendix E. Rotor speed and power turbine speed varied +2% during the maneuver. The T700-GE-701A engine/airframe response during pull-up and push over maneuvers is satisfactory.

STATIC DROOP CHARACTERISTICS

10. The static droop characteristics of the T700-GE-701A engine were evaluated by setting N_{R} to 100% then conducting a normal takeoff and IRP climb to 1000 feet, accelerating to V_{H} , diving to the limit airspeed in forward flight (V_{NE}) and returning to a hover. There was no static droop. Within the limited scope of this test, the static droop characteristics of the UH-60A with T700-GE-701A engines installed are excellent.

QUICK STOP

A section in property is second in section with the property section of the second sections.

11. The T700-GE-701A engine/airframe characteristics during quick stop maneuvers were evaluated in a level deceleration from $V_{\rm H}$ to a hover. The maneuver was performed by starting at $V_{\rm H}$, then

reducing the collective to essentially full down and adjusting the cyclic to maintain constant altitude above the ground. representative time history is presented in figure 10, appendix E. The rotor speed increased to 107% (within handbook limits of 110%) during the deceleration. The power turbine speed followed the rotor speed to approximately 103%, then split down to 100% until the collective was increased at the end of the flare. turbine speed then increased to 104% joining the decreasing rotor speed. The recovery at completion of the quick stop resulted in the Np drooping to approximately 92%. During the recovery, approximately 30 feet of altitude was lost while the engines were accelerating to hover power. The aircraft yawed to the left as initial collective pitch was applied then to the right as engines accelerated to hover power. The low rotor audio and visual warning systems activated. This caused the pilots attention to be diverted inside the cockpit and required extensive pilot compensation to complete the maneuver (HQRS 6). The slow engine acceleration characteristics and resulting rotor droop are shortcomings which degrade the mission maneuvering capability of the aircraft.

LONGITUDINAL FLARE DECELERATION

12. Longitudinal flare deceleration characteristics were evaluated at the conditions shown in table 1. The maneuver could not be completed with the collective fixed due to the increase in torque and turbine gas temperature (TGT) as the airspeed was reduced. A representative time history is presented in figure 11, appendix E. The T700-GE-701A/UH-60A engine response characteristics during collective fixed longitudinal flares are satisfactory.

JUMP TAKEOFF

13. T700-GE-701A/UH-60A jump takeoff characteristics were evaluated at two different rates of collective pulls to IRP. Representative time histories are presented in figures 12 and 13, appendix E. Although the rotor drooped to less than 95% causing the audio and visual warning to activate, the aircraft was climbing and clearing all obstacles, thus the pilot did not sense and in fact was not approaching a hazardous situation. The jump takeoff characteristics of the T700-GE-701A engines installed in the UH-60A are satisfactory.

ENGINE STABILITY

14. The T700-GE-701A/UH-60A engine/airframe stability characteristics were evaluated using separately, both pedal and collective

pulses. Representative time histories are presented in figures 14 through 16, appendix E. There was no indication of engine/airframe instability during either the collective or pedal pulses, and although not indicated by the time histories, the oscillations were highly damped when the control input pulsing was terminated. The T700-GE-701A/UH-60A engine/airframe stability response characteristics are satisfactory.

ENGINE ELECTRICAL CONTROL UNIT (ECU) LOCKOUT

15. The T700-GE-701A engine characteristics while operating in ECU lockout were evaluated by setting power for level flight at 80 KIAS, then placing one power lever in ECU lockout, and manually resetting that engine torque to match the governed engine. ECU lockout was easily attained and power lever adjustment to match torques was quickly and easily accomplished. A representative time history is presented in figure 17, appendix E. With the engine operating in manual control set as described above, the aircraft was accelerated to $V_{\rm H}$, decelerated to a hover, landed, and the collective reduced to full down. The torque matching provided by the load demand spindle was excellent when the power lever was set for level flight at 80 KIAS. The excellent torque matching engine stability and rotor speed control with one engine in ECU lockout and the power lever set for level flight at 80 KIAS enhances mission accomplishment when operating in a degraded mode. During previous T700-GE-700 engine evaluations the same characteristics have been noted. A discussion of this procedure should be included in the UH-60A handbook and should be taught and demonstrated during transition and refresher training.

CONTINGENCY POWER

16. The contingency power characteristics of the T700-GE-701A engines were evaluated at the conditions shown in table 1 with one engine power lever set at idle. Compared with the T700-GE-700 engine, the 701A engine two and one-half minute CRP provides a 10% increase to 1723 SHP at sea level standard day conditions and a 22% increase to 1443 SHP at 4000 ft 95°F day conditions. A time history of an increase to CPR is presented in figure 18, appendix E. For this test, the CPR had to be pilot limited at 917°C TGT due to adjustments made to the 401 ECU used on the test engine. The 917°C limit was easy to exceed and had to be closely monitored by the pilot. While operating at CPR, engine response was the same as when operating at normal and intermediate power settings. Only stable responses were noted. The additional power available for emergency single engine operations is enhancing to the safety and survivability of the crew and aircraft and should be incorporated in future designs.

MISCELLANEOUS

17. A popping sound subsequently determined to be "oil canning" at approximate fuselage station 262 on the right side of the fuselage was heard when collective was increased to approximately 80% torque or greater. According to Sikorsky support personnel, the fuselage skin in that area had been reinforced for the heavy weight tests, then the reinforcing structure removed upon completion of these tests. This oil-canning possibly represents a weak area of the fuselage and should be monitored for structural implications.

CONCLUSIONS

GENERAL

- 18. Based on the PAE of the T700-GE-701A engines installed in the UH-60A helicopter the following conclusions were reached:
- a. The operation of this engine installation was satisfactory except for the shortcomings noted below.
- b. The CPR available for emergency single engine operation enhances the safety and survivability of the crew and aircraft.
- c. Two enhancing characteristics and two shortcomings were identified.

ENHANCING CHARACTERISTICS

- 19. The following enhancing characteristics were identified:
- a. The added contingency power available for emergency single engine operations (para 16)
- b. The excellent torque matching engine stability and rotor speed control with one engine in ECU lockout and the power lever set for level flight at 80 KIAS (para 15)

SHORTCOMINGS

- 20. Two shortcomings were identified:
- a. The slow engine acceleration during collective pulls from approximately zero torque to 50% and greater torque and during aggressive maneuvers such as a quick stop from $V_{\rm H}$ (paras 7 and 11)
- b. The rotor droop to less than 95% Ng and resulting aircraft response during collective pulls from approximately zero torque to 50% or greater and during aggressive maneuvers such as a quick stop from $V_{\rm H}$ (paras 7 and 11)

RECOMMENDATIONS

- 21. The following recommendations are made:
- a. The shortcomings reported in paragraphs 7 and 11 be corrected.
- b. The enhancing characteristics noted in paras 15 and 16 be incorporated in future designs.
- c. A discussion of the ECU lockout procedures discussed in para 15 should be included in the UH-60A handbook and Aircrew Training Manual (ATM).
- d. Monitor the oil canning for structural implications (para 17).

APPENDIX A. REFERENCES

- 1. Letter, AVRADCOM, DRDAV-DI, subject: Preliminary Airworthiness Evaluation of the UH-60A Helicopter with T700-GE-701A Engines Installed. (Test Request)
- 2. Prime Item Development Specification, DARCOM CP-2222-S1000F, Redline Markup for T700-GE-701A Engine Qualification Effort 7 June 1983.
- 3. Model Specification, Red Line Mark-up for T700-GE-701A Engine, 31 May 1983.
- 4. Technical Manual, TM55-1520-237-10, Operator's Manual, UH-60A Helicopter, 21 May 1979, with change 19 dated 14 February 1983.
- 5. Letter, AVRADCOM, DRDAV-D, 23 June 1983, subject: Airworthiness Release for the conduct of a Preliminary Airworthiness Evaluation of the UH-60A Helicopter with the T700-GE-701A Engines Installed, Project No. 83-17.
- 6. Letter, USAAEFA, DAVTE-TB, 22 June 1983, subject: Test Plan Preliminary Airworthiness Evaluation of the UH-60A Helicopter with the T700-GE-701A Engines Installed, USAAEFA Project No. 83-17.
- 7. Paper, Anderson, William A., "Suggested Requirements for Military Helicopter Gas Turbine Engine Operating Charcteristics", published in Journal of the American Helicopter Society, Vol 12, No. 2, April 1967.

ALCO LECTER PERSONAL SERVICE SECRETAR SECRETAR REPORTS BETWEEN RESIDENCE SECRETAR SE

8. Army Material Command Pamphlet, AMCP No. 706-203, Engineering Design Handbook, Helicopter Engineering Part 3 Qualification Assurance April 1972.

APPENDIX B. ENGINE DESCRIPTION

- 1. The T700-GE-701A engine is a front drive, turboshaft engine featuring a single-spool gas generator section consisting of a five-stage axial, single-stage centrifugal flow compressor, a through flow annular combustion chamber, a two-stage axial flow gas generator turbine, and a free or independent two-stage axial flow power turbine. The power turbine shaft, which has a rated speed of 20,900 revolutions per minute (RPM), is co-axial and extends to the front end of the engine. The engine also incorporates modular construction throughout, an integral inlet particle separator, a top-mounted accessory package, an engine-driven fuel boost pump, a selfcontained lubrication system, condition monitoring-diagnostics provisions, a hydromechanical gas generator control system, and an electrical power control system providing power turbine speed control, dual engine load sharing, and redundant power turbine overspeed protection.
- 2. The T700-GE-701A engine has a contingency power (2.5 min.) rating (CPR) for use under one-engine inoperative conditions. Contingency power available for pilot use was manually selectable on the test aircraft. The production installation will automatically provide contingency power under single engine operation when a failed engine torque goes below 50%. The T700-GE-701A engine also has a 10 minute limit rating in addition to the 30 minute limit and the 2.5 minute limit.

THE THE PROPERTY OF THE PROPER

3. The T700-GE-701A engine core has longer first stage compressor blades and increased cooling air flow to the turbine buckets. resulting in the turbine buckets seeing the same temperature as the T700-GE-700 engine. The proposed 701A standard engine instrumentation eliminates the oil temperature indicating system and incorporate a AP oil pressure indicating system referenced to the internal B-sump pressure. The T700-GE-700 engine has overspeed protection at 106% power turbine speed (Np) which cycles the fuel flow between minimum and maximum. The T700-GE-701A engine has overspeed protection which cuts off all fuel flow at 120% Np. The -700 engine has a sea level standard day 30 minute intermediate power rating of 1561 shaft horsepower (SHP); the 701A engine has a sea level standard day 30 minute IRP limit of 1694 SHP and a 2.5 minute CPR of 1723 SHP. The -700 engine has a hot day (4000 feet, 95°F) 30 minute rating of 1181 SHP; the 701A engine has a hot day 30 minute limit of 1295 SHP, a 10 minute limit of 1350 SHP and a 2.5 minute CPR of 1443 SHP. Engine turbine gas temperature (TGT) limits for the -700 engine are 775°C continuous, 850°C for 30 minutes, and 886°C for 12 seconds. TGT limits for the 701A engine are 801°C maximum continuous, 867°C for 30 minutes, 872 +5° for 10 minutes (electrical control unit (ECU) limited) and 917°C for 2.5 minutes CPR (pilot limited on test aircaft, ECU limited on production aircraft).

APPENDIX C. INSTRUMENTATION

GENERAL

1. The test instrumentation was installed, calibrated and maintained by Sikorsky Aircraft Division Personnel. A test boom, with a swiveling pitot-static tube and angle-of-attack and sideslip vanes, was installed on the nose of the aircraft. Data was obtained from calibrated instrumentation and displayed or recorded as indicated below.

Pilot Panel

Airspeed (boom) Altitude (boom) Altitude (radar) Rate of climb (boom) Rotor speed (sensitive) Engine torque ** Turbine gas temperature (T4.5)** Power turbine speed (Np)** Gas generator speed (Ng)** Control position Longitudinal Lateral Directional Collective Horizontal stabilator position Normal acceleration at cg Angle of sideslip

Copilot Panel

Airspeed (ship)
Altitude (ship)
Fuel remaining
Free air temperature
Time code display
Run number

2. Data parameter recorded on board the aircraft include the following:

Digital (PCM) Data Parameters

Power turbine speed $(Np)^{**}$ Gas generator speed $(Ng)^{**}$

**Both engines

```
Turbine gas temperature (T4.5)**
Main rotor speed
Fuel used **
Engine torque**
Power available spindle position**
Load demand spindle position**
Fuel flow**
Main rotor shaft extension torque
Tail rotor torque
Tail rotor impressed pitch
Control position
   Longitudinal
   Lateral
   Peda1
   Collective
Horizontal stabilator position
Sideslip angle
Angle-of-attack
Aircraft attitude
   Pitch
   Roll
   Yav
Angular Velocity
   Pitch
   Roll
   Yaw
Angular acceleration
   Pitch
   Roll
   Yaw
Normal load factor @ cg
Airspeed (boom)
Airspeed (ship)
Altitude (boom)
Rate of climb (boom)
```

**Both engines

APPENDIX D. TEST TECHNIQUES AND DATA ANALYSIS METHODS

GENERAL

CONTRACTOR AND ASSESSMENT

Lawrence Contract Contract Contract

1. The T700-GE-701A engine handling characteristics were evaluated using the basic methods described in references 7 and 8, appendix A. All test data were recorded using test instrumentation and recorded on magnetic tape installed in the aircraft. The data are presented as time histories of pertinent engine parameters.

ENGINE ACCELERATION

2. The T700-GE-701A engine acceleration characteristics were evaluated using dual and single engine collective pulls to Intermediate rated power (IRP) from predetermined power settings. These power settings varied incrementally from 80 percent torque down to sero torque (autorotation). The target rates of application were for a ramp input varying from five to one seconds. The aircraft was stabilized at the test altitude and airspeed. The data recorder was turned on, the ramp input completed, and the dynamic response was recorded. On those points where the rotor drooped to less than 95 percent, the collective was reduced to effect recovery when the low rotor speed visual and audio warning were observed.

RIGINE DECELERATION

3. The T700-GE-701A engine deceleration characteristics were evaluated using dual and single engine collective ramp reduction to full down collective. The aircraft was stabilized, the data recorder activated, and the input completed as described in paragraph 2.

PULL-UP AND PUSH-OVER

4. The T700-GE-701A engine response during pull-up and push-over maneuvers was evaluated by stabilizing the aircraft in level flight, turning the data recorder on and applying an aft cyclic input to decelerate the aircraft followed by a forward cyclic input to accelerate the aircraft to a nominal speed above the stabilized airspeed.

STATIC DROOP

5. The T700-GE-701A engine static droop characteristics were evaluated by setting the rotor speed to 100 percent on the ground

at flat pitch, then performing takeoff, IRP climb, level flight maneuvers, autorotational descent and landing while observing the static changes in rotor speed during the various flight configurations.

QUICK STOP

6. The T700-GE-701A engine response characteristics during quick stop maneuvers were evaluated by accelerating to maximum level flight airspeed, turning on the data recording system, then reducing the collective to the full down position while applying aft cyclic to maintain constant altitude. The data are presented as a time history of pertinent engine parameters.

LONGITUDINAL FLARE DECELERATION

7. The T700-GE-701A engine response characteristics during longitudinal flare decelerations were evaluated by accelerating to maximum level flight airspeed, turning on the data recording system, performing a collective fixed deceleration by applying aft cyclic, and allowing airspeed and altitude to vary until the airspeed decreased to zero.

JUMP TAKEOFF

8. The T700-GE-701A engine response characteristics during jump takeoffs were evaluated by applying collective until the aircraft was light on wheels, turning the data recording system on, then making a ramp collective input to the IRP setting. Varying rates of application were evaluated as a buildup to a one second ramp input to IRP.

ENGINE STABILITY

9. The T700-GE-701A engine stability characteristics were evaluated by stabilizing the aircraft in level flight, turning on the data recording system and applying collective and pedal pulses at various rates until the apparent natural frequency was determined. The controls were then pulsed at this rate for several seconds to determine if any divergent oscillation characteristics were present. The collective was returned to the initial setting (mean of the pulse input) and the damping characteristics were evaluated prior to turning off the data recorder.

ENGINE ELECTRICAL CONTROL UNIT LOCKOUT

10. The T700-GE-701A engine and rotor speed response characteristics while operating in ECU lockout were evaluated by stabilizing in level flight at 80 knots indicated airspeed (KIAS). The data recorder was turned on, one engine placed in ECU lockout and the locked out engine set at various power settings above and below the ECU controlled engine. The locked out engine was then torque matched to the other engine, the aircraft accelerated to maximum level flight airspeed, then decelerated to approach speed, hover, and landing with the collective placed at flat pitch without resetting the locked out engine power lever.

CONTINGENCY POWER


11. The T700-GE-701A contingency power characteristics were evaluated by stabilizing the aircraft in level flight, placing one engine power lever to idle, turning on the data recorder, activating the pilot controlled contingency power switch and increasing collective to contingency power limits. The limits had to be pilot monitored due to the test engine configuration (see engine description, app B).

DEFINITION

12. The following definition of a shortcoming was used during this evaluation: Shortcoming - An imperfection or malfunction occurring during the life cycle of equipment which must be reported and which should be corrected to increase efficiency and to render the equipment completely serviceable. It will not cause an immediate breakdown, jeopardize safe operation, or materially reduce the useability of the material or end product.

HANDLING QUALITIES RATING SCALE

13. A Cooper-Harper Handling Qualities Rating Scale (HQRS) (fig. 1) was used to augment pilot comments relative to handling qualities.



Marks Some

Pigure 1. Handling Qualities Rating Scale

APPENDIX E. TEST DATA

<u>Figure</u>	Figure Number	
Engine Acceleration	1 through 6	
Engine Deceleration	7 and 8	
Pull-up and Push-over	9	
Quick Stop	10	
Longitudinal Flare Deceleration	11	
Jump Takeoff	12 and 13	
Engine Stability	14 through 16	
BCU Lockout	17	
Contingency Power	18	

FIGURE 1
DUAL ENGINE COLLECTIVE PULL





FIGURE 2

DUAL ENGINE COLLECTIVE PULL



"IGURE 3
SINGLE ENGINE COLLECTIVE PULL




FIGURE 4
SINGLE ENGINE COLLECTIVE PULL




FIGURE 5

SINGLE ENGINE COLLECTIVE PULL






FIGURE (

DUAL ENGINE COLLECTIVE PULL



1 TGURE 7

DUAL ENGINE DECELERATION






FIGURE 9
PULL-UP AND PUSH-OVER MANEUVER




FIGURE 10
QUICK STOP MANEUVER




FIGURE 11

LONGITUDINAL FLARE DECELERATION MANEUVER




FIGURE 12

JUMP TAKEOFF




FIGURE 13

JUMP TAKEOFF




FIGURE 14
COLLECTIVE PULSES




FIGURE 15

PEDAL PULSES







FIGURE 16

COLLECTIVE PULSES





CPR OPERATION



DISTRIBUTION

Deputy Chief of Staff for Logistics (DALO-SMM, DALO-AV)	2
Deputy Chief of Staff Operations (DAMO-RQ)	1
Deputy Chief of Staff for Personnel (DAPE-HRS)	1
Deputy Chief of Staff for Research Development and	
Acquisition (DAMA-PPM-T, DAMA-RA, DAMA-WSA)	3
Comptroller of the Army (DACA-EA)	1
US Army Materiel Development and Readiness Command	
(DRCDE-SA, DRCQA-E, DRCDE-I, DRCDE-P, DRCQA-SA, DRCSM-WA)	6
US Army Training and Doctrine Command (ATTG-U, ATCD-T,	
ATCD-ET, ATCD-B)	4
US Army Aviation Systems Command (DRSAV-ED, DRSAV-EI,	
DRSAV-EL, DRSAV-EA, DRSAV-EP, DRSAV-ES, DRSAV-Q,	
DRSAV-MC, DRSAV-ME)	16
US Army Test and Evaluation Command (DRSTE-CT-A,	
DRSTE-TO-O)	2
US Army Logistics Evaluation Agency (DALO-LEI)	1
US Army Materiel Systems Analysis Agency (DRXSY-R, DRXSY-MP)	2
US Army Operational Test and Evaluation Agency (CSTE-POD)	1
US Army Armor Center (ATZK-CD-TE)	1
US Army Aviation Center (ATZQ-D-T, ATZQ-TSM-A,	
ATZQ-TSM-S, ATZQ-TSM-U)	4
US Army Combined Arms Center (ATZLCA-DM)	1
US Army Safety Center (IGAR-TA, IGAR-Library)	2

US Army Research and Technology Laboratories (AVSCOM)	
(DAVDL-AS, DAVDL-POM (Library))	2
US Army Research and Technology Laboratories/Applied	
Technology Laboratory (SAVDL-ATL-D, SAVDL-Library)	2
US Army Research and Technology Laboratories/Aeromechanic	18
Laboratory (AVSCOM) (SAVDL-AL-D)	2
US Army Research and Technology Laboratories/Proplusion	
Laboratory (AVSCOM) (SAVDL-PL-D)	1
Defense Technical Information Center (DDR)	12
US Military Academy (MADN-F)	1
MTMC-TFA (MTT-TRC)	1
ASD/AFXT	1
Project Manager, BLACK HAWK (DRCPM-BH)	5
US Army Aviation Development Test Activity (STEBG-CT)	2
US Army Infantry Center (ATSH-TSM-BH)	2
US Army Material Systems Analysis Agency (DRXSY-AAM)	2
US Army Operational Test and Evaluation Agency	
(CSTE-TM-AV)	2:
General Electric (Mr. Koon)	2
Sikorsky Aircraft Division, United Technologies	
Corporation (Mr. Richard Connor)	5